

Te Puke Sports Grandstand

Before and After, Minor Defect Schedule and Construction Photo Record
Atuaroa Avenue, Te Puke 3119

Before and After





Minor Defect Schedule

21-12-20




Resolution to Differential in Cladding Colour/Appearance to Rear Wall



Residue Galvanising Slag to be Removed and Local Galve Repair as Required



Intermediate Purlin Brackets to be Replaced




Staining/Acid Rust to be treated and Joint sealed (PFC to Flat Plate)



Bird Proofing Solution for Two Corners of Grandstand Roof



Three Char Damaged Timbers to be Replaced



Short One Pedestal

Contract Works to Complete

1. Stormwater Drainage, Soak Pits to Rear of Grandstand

2. Tactile Buttons to Accessible Handrails
3. Maint Check on Bolts Post Construction

Credits to be Processed

1. Free Issue Timber From Te Puke Sports
2. No Bird Proofing Foam Sealing Strip Required Front and Rear of Roof
3. No Roof Netting Required
4. Minor Eletrical Trenching Completed by Murray Salt

Photo Record - Key Construction stages







